

# ZC-B100

# Smart Clamp Meter



**4000 Counts**

### Standard Accessories

1. 2 x Battery
2. 2 x Test lead
3. 1 x Standard user manual
4. 1 x Black soft case
5. 1 x Wrist strap



Specifications	Range	Accuracy
DC Voltage	4.000V/40.00V/400.0V/600.0V	$\pm(0.5\%+3)$
AC Voltage	4.000V/40.00V/400.0V/600.0V	$\pm(1.0\%+3)$
AC Current	4.000A/40.00A/400.0A/600.0A	$\pm(2.0\%+30)$
Resistance	4.000k $\Omega$	$\pm(1.5\%+3)$
	40.00k $\Omega$ /400.0k $\Omega$ /4.000M $\Omega$	$\pm(0.5\%+3)$
	40.00M $\Omega$	$\pm(1.5\%+3)$
Frequency	4.000Hz/40.00Hz/400.0Hz/4kHz/40kHz/100kHz	$\pm(0.5\%+5)$
Continuity	●	
NCV	●	

Features		
Auto ranging	True RMS	Data hold
Backlight/Flashlight	Low battery alert	Auto power off
Inrush current	Peak Hold	
General		
Power Supply	2 x 1.5V AAA Battery	
Dimension	172*64*32mm	
Weight	161g	