

ZC-B400

Smart Clamp Meter



4000 Counts

Standard Accessories

1. 2 x Battery
2. 2 x Test lead
3. 1 x Standard user manual
4. 1 x Black soft case
5. 1 x Thermocouple probe
6. 1 x Wrist strap

Specifications	Range	Accuracy
DC Voltage	4.000V/40.00V/400.0V/600.0V	$\pm(0.5\%+3)$
AC Voltage	4.000V/40.00V/400.0V/600.0V	$\pm(1.0\%+3)$
AC Current	4.000A/40.00A/400.0A/600.0A	$\pm(2.0\%+30)$
Resistance	4.000k Ω	$\pm(1.5\%+3)$
	40.00k Ω /400.0k Ω /4.000M Ω	$\pm(0.5\%+3)$
	40.00M Ω	$\pm(1.5\%+3)$
Capacitance	4.000nF	$\pm(5.0\%+20)$
	40.00nF/400.0nF/4.000 μ F/40.00 μ F/400.0 μ F	$\pm(2.0\%+5)$
	4.000mF	$\pm(5.0\%+5)$
Frequency	4.000Hz/40.00Hz/400.0Hz/4kHz/40kHz/400kHz/1MHz	$\pm(0.5\%+5)$
Temperature	-30°C~1000°C/-22°F~1832°F	
Diode/Continuity	●/●	
NCV	●	
Features		
Auto ranging	True RMS	Data hold
Backlight/Flashlight	Low battery alert	Auto power off
Inrush current	Peak Hold	Smart mode
General		
Power Supply	2 x 1.5V AAA Battery	
Dimension	172*64*32mm	
Weight	161g	